

Is the shaft now fitted new?

No

Has it a continuous liner?

or two liners?

Fol. 4577

Aux. No. 100 5 met 3. "A.C. Hanson


It is submitted The Southampton
Surveyors should be requested
to state the reasons for the
renewal of the Starboard Engine

ARRR

9. 8. 20

Repairs effected:-

No 3 cylinder renewed.



© 2020

W656-0282 Lloyd's Register
Foundation