

1023.

W657-0163

3

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

*At Sea Courtown*

Rpt.

*Off*

No.

*45738*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey

S.S. No. *3* AND DAMAGE

Damage through

*Striking quay & grounding*

now repaired as follows:-

	Plates	Frames	R.Frames	Floors	Beams	Str.	Plates	Dk.	Plates
Renewed .....									
Removed and faired or repaired.....	<i>1</i>								
Faired or repaired in place.....	<i>2</i>	<i>3</i>							

Other items:-

*Vessel placed in Dry Dock and minor repairs effected.*

*A* The S.S. No. *3* has also been held and following repairs done due to wear and tear:- *Bottom recoated & minor repairs carried out*

It is submitted the vessel is worthy to remain classed with record of Survey *8. 24* and notation of *SS Hull No. 3. 4. 24* as recommended.

*100 A. 1 Shells OK with feet*  
*8. 24 Off*  
*SS Hull No. 3. 4. 24*



*18.9.24*  
Lloyd's Register Foundation