

2m, 3, 10.

6838.67

1

Sent to Chief Surveyors

8/4/11

Received from Chief Surveyors

VESSEL'S NAME *Stl. S. S. Highland Loch* Report *Liv.* No. *65661*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

1st Entry

When due

✱ 100 A1 ("Stel") "Shelter deck with freeboard"

3 Dks (stl.) & Shelter Deck (stl.)

WB = all DB = 130' & EYB 63' f 167' 1234^l. FPT 129^l. APT 23^l.

FK 8 BH. "Collision bulkhead to upper deck only" am. Lloyd's A+C.P.

Lloyd's Register
Foundation

W658-0001

Poop Deck, Angle, Bulk Angle, Rate,
Tee Bulb or Channel
Angles on upper edge
Sagging

Deck, Material and thickness *STEEL*
Poop Deck Stringer Plate, breadth & thickness
Angles on ditto
Tie Plates