

F.E.

Received by Chief Ship Surveyor 27. 3. 08

Received from Chief Ship Surveyor

VESSEL'S NAME St. Steam Trawler "Salvador" Rpt. Steel No. 19911

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>1 1/2" in line of 2 1/2"</u>	<u>Not required</u>
Spar Sheerstrake . .		
Description of Framing:— <u>Bulb angle, as approved</u> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \dagger 100 A 1 ("Steel") "Steam Trawler" as recommended.

\dagger 100 A 1 ("Steel") "Steam Trawler"
18x.

N. B = DBf33' 326 APT 126

BK 7 1/2" 5BH Asp. Lloyd's A & CP Q 79' F24'



© 2001

27/3/08
Lloyd's Register
Foundation
W660 - 0034