

REPORT of SURVEY for REPAIRS, &c.

Writing Report 20th Mar. 25 When handed in at Local Office 20th Mar. 25 Port of Bordeaux
Survey held at Bordeaux Date, First Survey 10th Feb. Last Survey 13th Mar. 1925
Book. (No. of Visits 4)

Material of the Vessel Wood, Iron or Steel S.S. - LABRADOR.
Tonnage: - Built at Selby. By whom Cochran & Sons. When 1908. 3.
Gross 399 Owners Joe. Hunt. Owners' Address
Net 360 Managers ✓ (if not already recorded in Appendix to Register Book).
Deck 154 Port belonging to Bordeaux.

Surveyed Afloat or in Dry Dock? Yes. Name of Dock Bordeaux. Destined Voyage Newfoundland (via New York, N.Y.)
Cell DBor DBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
Capacity tons. FPT tons; APT tons; MT feet tons. }

N.B. - All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, etc., and of the inner bottom plating, especially in the boiler space.

Special Report, No. 3320 Port Bdx

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned and now expired.	Machinery and Boiler Survey (including date of N.B., if any).
+100 A1 Steel trawler.	4.24	+ LMC 4.21
S.S. Bdx. 2.3-4.21		B.S. 4.24 T.S. 3.24, 6.4.
-		-
-		-
-		-

Medical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the nature of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the movement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on back of this form. State also the dates and initials of any letters respecting this case.
13th Jan. 1925
Damage cases where the Surveyor has not made a special damage report he is required to state whether he rendered his services for this purpose and to whom and why they were declined.

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom? ✓
LOCKING and Condition.

Essel placed in dry dock.
Bottom and Judder cleaned. Framing and Jucosats.
How done for wear and tear:-
Judder lifts and Rattles renewed.
Steering gear, rods, chains and connections overhauled.
Several shell rivets renewed on port side forward - as four foot.
All riveting and caulking overhauled on Starboard side aft.
Stiction boards on upper deck partly renewed.
undry minor repairs.

DESCRIPTION OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
ed								
ed and Faired or Repaired								
ed Repaired in place								

CONDITION OF THE	State if Tanks have been examined inside	Dblg. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.)
Good.	State if Tanks now tested	Engine Room Skylights	When put on, Month Year
"	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Boats
Good.	Ceiling	Scuppers	Masts, Yards, &c.
"	Cement or Asphalt (State which.)	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
"	Rudder	Hatches	Sails
"	Steering gear and its connections	Planking of Wood Vessels	Equipment letter
"	Windlass	Caulking ditto	Anchors, No. of
"	Have Pumps now been examined and found efficient?	Treenails ditto	Cables (State if now ranged)
"	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	length 165 fms size 1 3/16"
"	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Rule length 120 fms size 1 3/16"
"	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Rule length 120 fms size 1 3/16"
"		Ditto ditto at other places ditto	Hawser & Warps
"		Stringers, Clamps & Shelves ditto	Standing & Running Rigging
"		Salting (State if examined.) ditto	

Observations, Opinion as to Class, Recommendation, &c.:-
The vessel being in an efficient condition is eligible in our opinion to remain as classed and to have record of Survey, 3-25.

Section 20) 30. 194. - Fees applied for, 20.3.1925
Repair Fee (if any) 2 Received by me, 19
Fees (if chargeable) 5. - 30.199. -
Fee (if any) ✓

FRI. 27 MAR 1925
Assigned note
1000s Star Trawler
B.S. 3.25
Surveyor to Lloyd's Register of Shipping.
FRI. 27 AUG 1925
Lloyd's Register Foundation
W660-0639