

F.E.

Received by Chief Ship Surveyor 24. 9. 06

Received from Chief Ship Surveyor

VESSEL'S NAME See S.S. "Witiaz"Report Ans. No. 7165

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>2 1/2" deep, but compensated by increased thickness of strake above and below.</u>	
Spar Sheerstrake . .	<u>2 1/2"</u>	<u>Proportions</u>
Description of Framing:— <u>Channel.</u> (viz., ordinary, deep, zed, channel or bulb-angle).		

The Kedge anchor is 5 lbs. less in weight than required by Table 22.


In other respects This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + 100 A1 ("Steel") "Spar deck with freeboard," as recommended. The Summer freeboard of 5' 10 1/2" from centre of disc to top of statutory deck line at Spar deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

+ 100 A1 ("Steel") "Spar deck with freeboard."

1 DR (SEA) & Spar DR. & web frames.

W. B = All DB a 63' u E 78 60' f 90' 325 C

FK 5BH Can. Lloyd's A & CP P 55' B 66' F 50'



© 2021

Lloyd's Register
Foundation

W660-0116

24/9/06