

Surveyors _____

Received from Chief Surveyors _____

NAME *S.S. "Spain Maru"* Report *Bal* No. *3683*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report 24/5/92.*

by *Repairs.* When due _____

Subject:- The indented plating, etc. on starboard side and damaged bottom plating, etc. to be dealt with at the Owners' convenience, and the stern frame and rudder repaired by electric welding in November 1921 to be specially examined at the next dry docking.
To complete the s.s.No.1 due 12,23 the engine and boiler room tank requires to be tested and examined and the bunkers to be examined.



© 2021

W.H.
Lloyd's Register
Foundation

W660-0190