

It is submitted that before this case receives the consideration of the Committee it should be pointed out to the Surveyors that according to their first entry report the thickness of D strake of plating in way of margin plate of double bottom appears to have been reduced $1/20"$ in thickness from the thickness shown on the approved sketch of midship section and contrary to the Rules. They should therefore be requested to state whether the thickness shown on their report is the thickness of the strake as fitted in the vessel or whether it is in error.

Rev. to Dtd. 21/4/04.

C. H. J.
21/4/04



© 2020

Lloyd's Register
Foundation

W666-0190

Poop Deck Stringer Plate, breadth & thickness										38	
Average space										3 1/2 x 3 1/2	
Poop Deck Stringer Plate, breadth & thickness											
Angle on ditto											