

Less Crew Space 11.2
Less above Crown of 4
Engine Room . . .

Chief Ship Surveyor 18.9.16

Received from Chief Ship Surveyor

NAME Steel S. S. Wilton Rpt. Hpl No. 15291

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Survey 1st Entry

It is submitted that before this case receives consideration the report should be returned to the Surveyors who should be requested to have it signed by the builders.

Lt. Hpl 18/9/16
+ 7.8. Rpt.

M
A.P.
18.9.16



© 2020

Lloyd's Register
Foundation

W667-0065