

28 MAR 1930

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Steel Sc.Sr. "SEIYO MARU".

Rpt.

Kob.

No. 6835

Acts of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

vey

The class is subject to No.1 keel plate and Nos. 4 and 5 plates in F strake on port side and indented plating on port and starboard sides being dealt with at the Owners' convenience.

The Kobe Surveyors now report the vessel placed in dry dock and the bottom coated.

The indented shell plating has not been dealt with.

No.3 hatchway at the main and shelter decks has been enlarged in accordance with an approved plan.

It is submitted the vessel appears worthy to remain as classed with record of survey 2,30, subject as above.

OOA1)
shelter deck with freeboard.) subject etc.
2,30 Kob.)



© 2020

Lloyd's Register
Foundation

28.3.30.
No. 6835