

Less Engine Room 2077.34  
Less Navigation Spaces 70.08

Deck at side to top of keel  
" " Upper Deck at side

13.49

Residence

Part belonging to

Yokohama

1

Sent to Chief Surveyors

20/8/13

Received from Chief Surveyors

VESSEL'S NAME

Itt Ss Teiyo Maru

Report

Grn

No. 16520

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.)—Extract from Sub-Committee's Report, 24/5/12

Nature of Survey

121 entry

When due

± 100A-1. (etd) Shelter deck with foreboard.  
2 D<sup>ns</sup> (etd) + Shelter deck (etd - W.S.)

N.B. = bull DB a 12' w E 24' f 184 1125L F.P.T 1176 A.P.T 284

FK OBH Cam Lloyds A & C.P.

M

20/8/13

20/8/13

W 671-0150



© 2020

Lloyd's Register  
Foundation

Spacing  
BEAMS, Bridge Deck, Angle, Bulb Angle, Plate,  
Tee Bulb or Channel

Plating, Deck Stringer Plate, breadth & thickness

Angle on ditto