

of ANTWERP.

23rd March 1922.

JOHN THOMSON

the Captain, survey the S/S "TICHAMARA", 173 tons gross, of London, whilst the vessel was lying in the City Dry Dock at Antwerp, where she had been placed for examination and repairs, on the 4th March 1922 and subsequent dates, for the purpose of ascertaining the nature and extent of the damage stated to have been sustained on the 2nd March 1922 through the propeller striking some submerged object whilst on the voyage from London to Antwerp.

For further particulars see Log Book.

UPON EXAMINATION:

FOUND:

One blade of propeller broken off. Tail shaft to be drawn

RECOMMENDED:
in for examination and to be put in the lathe, also short length of intermediate shaft to be tried in lathe and line of shafting to be examined.



J.T.
© 2020

Lloyd's Register
Foundation

Re:
Hor:
No.
No.
Ste:

2.

FOUND:

RECOMMENDED:

Stern bush to be rewooded.

ALSO RECOMMENDED that all fittings removed to effect or facilitate these repairs be replaced as before; and the whole of the work be carried out in such a manner so as to place the machinery of this vessel in the same good and efficient condition as it was in prior to the alleged damage.

Fee. Frs. 312.-

John Thomson

Surveyor to Lloyd's Register, Antwerp.



© 2020

Lloyd's Register
Foundation

W672-0209-070