

5m.2.15.

1

Sent to Chief Surveyors

6.11.16.

Received from Chief Surveyors

VESSEL'S NAME

Miss Tighnamara

Report

don

No.

79332

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

Miss No 3

When due

6.16.16 held

The class of this vessel is subject to the sea  
cocks in fore hold being removed when vessel is dry docked.

A letter has now been received from the Owners  
in which they state they are experiencing difficulty in arranging  
for a dry dock, but they presume they will be in order in making  
one or two trips to Boulogne pending their being able to fix  
upon a dry dock.

It is submitted action be deferred.

8. 11. 16

To Complete Darry. Vessel to be  
examined in Dry Dock & sea  
cocks removed

LR

© 2020

Lloyd's Register  
Foundation

W672-0218

W672-0220