

Twice Bilge Diagonal from top of Upper Deck
Beam at centre to the moulding edge of Frames
(as per Rule)

20.33

Residence 25 Balm...

TELEGRAMS: "RAPIDO."
TELEPHONE, No. 135.

GARVEL SHIPYARD,

GREENOCK 28th Decr 1903

The Surveyor to Lloyd's Registry
Greenock -

N^o 22

Dear Sirs.

We shall be obliged by your
informing us if the following Equipment
would be considered ample for the above
vessel - viz:

2 Bower Anchors	Stockless	4 1/2 cwt
1 Stream "	Trotman	1 cwt ex stock
135 fathoms	12/16 Stud chain	cable
60 fathoms	5" Hawser (in lieu of Stud chain)	
75 fathoms	6" "	
75 "	4" "	

A reply at your convenience will oblige

Yours very truly
Geo Brown & Co



© 2020

Lloyd's Register
Foundation

W572-0260 261

"	"	Spacing	22	22	22	22	22	22
"	"	Pillars to Upper Deck Beams, size and spacing	2	44	2	44	2	44
"	"	MAIN DECK						
"	"	Cabin Sole Stringer Plate, breadth and thickness						
"	"	Angles						