

COPY.

22nd July, 1932.

MIDDLESBROUGH.

14681, "LEIGHTON". A fresh record of survey 7,32 has been assigned, together with notations of S.S.No.2-30, LMC.1,30, subject to indented plating etc. being dealt with, and to the pumps and pumping arrangements and electrical installation being examined. A record of DBS.6,32 will be assigned when the safety valves have been adjusted.

14683, 87. As recommended.

14685, "BLOEMFONTEIN". The Committee note from your report that this vessel has been generally examined, the starboard boiler surveyed and necessary repairs effected to both main boilers in accordance with the terms of my letter of the 4th instant, and that you have issued an interim certificate to enable the vessel to proceed to an Italian port to be broken up.

In view of my telephone message to you on Friday last respecting



© 2020

Lloyd's Register
Foundation

(22-7-32)

("BLOEMFONTEIN")

the amended form of certificate with which the Owners desired to be furnished and which it is understood you forwarded direct to them, I shall be glad to receive a copy of the same for attachment to your report, as one does not appear to have come to hand.



© 2020

Lloyd's Register
Foundation

W673-0230 1/2