

Port of Sunderland

June 29<sup>th</sup> 1932

REPORT ON MASTS, SPARS, AND RIGGING.

Dear Sirs

Having, in accordance with your instructions, examined the Masts, Spars, Iron Work of same, and Rigging, of the  
of Vessel SS Lady Astley lying Greenwell's Dock Sunderland  
the (Date of examination) June 29<sup>th</sup> 1932,  
we to report that I found Fore Rigging Port and Starboard  
2, 3 Shrouds in Starboard Main, N<sup>o</sup> 1 & 2 Shrouds  
Port Main Rigging. Port Main Topmast Backstay  
in Topmast stay, Wasted and in poor condition  
board N<sup>o</sup> 2 Perruck decayed at the Shoe end  
recommend the renewal of the above. Topping left  
and Eye Plates at Fore Mast Head worn in the nepe  
recommend the same to be repaired. Further recommend  
all Rigging screws, and Lower Shackles. Perruck  
Bolts, Large Bolts, and Links, be annealed and made  
to other spars. Rigging and Ironwork in good  
condition. Mast Wedges not out

£ : :

The Surveyors,  
Lloyd's Register of Shipping,

Sunderland



© 2020

R D Pearson

Lloyd's Register  
Foundation

W676-0021