

13 DEC. 1921

Chief Ship Surveyor

Received from Chief Ship Surveyor

S NAME Wood S.S. "MANLIO". Rpt. Nap. No. 2062

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

The class of this vessel is subject to a Special Survey equal to a Half Time Survey being held at four and eight years from date of build, and to <sup>the</sup> stream anchor being replaced by one of proper weight and test.

The Naples Surveyors now report the vessel placed in dry dock bottom cleaned and coated and the outside planking and deck recaulked.

It is stated that some steel wire is missing.

It is submitted the vessel appears worthy to remain as classed with record of survey 12,21, subject as above, and subject to the equipment of hawsers and warps being examined and found or placed in order.

12A1  
12,21 Mes. } subject etc.



© 2021  
19.12.21.

Lloyd's Register  
Foundation

W678-0060