

Lloyd's Register of Shipping,

3, Steinhoeft,

Hamburg, 10th May, 1928

10 APR 1928
LONDON



Dear Mr. Carnaghan,

In Hamburg First Entry Report No 17971 dealing with the electric installation on the motor vessel "PACIFIC PRESIDENT" an error has occurred in reporting the particulars of the equaliser connections of the main generators, the report giving one conductor 240 mm² instead of two conductors of 185 mm² each. The latter sizes were approved by you on the 7.12.27.

In the case of Hamburg First Entry Report No 18047 on the m.v. "PACIFIC GROVE" the sizes of the equaliser connections are correctly given. Perhaps you will be good enough to have the necessary corrections made to the "Pacific President" report. With kind regards, Yours sincerely

J. Chisholm

J. Carnaghan Esq.,

LONDON



© 2019

Lloyd's Register
Foundation

W68-0068