





Port of G E N O A

Continuation of Report No 43293 dated 16/2/1934.

S.S. "S A N T O N I".  
on the

Examined the Port and Starboard forward boilers together with safety valves and mountings and found same generally in good condition: afterwards examined the Port forward and Aft boilers under steam and adjusted their safety valves as above.

A.G.



© 2020

Lloyd's Register  
Foundation



Worked the Port and Starboard Forward Bolsters together with safety valves  
and mountings and found them generally in good condition. Afterward examined the  
Port forward and aft bolsters under steam and adjusted their safety valves as above.

RETAI

RETAI

