

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 23 July 31 When handed in at Local Office 23/7/31 Port of SINGAPORE
 No. in Reg. Book 88126 Survey held at SINGAPORE Date, First Survey 20 July 31 Last Survey 22 July 1931
 on the Wool, Iron or Steel M.V. "VULCANUS" (No. of Visits 2)

TONNAGE— Built at Amsterdam By whom Nederl Scheps Maats YEAR. MONTH. When 1910 - 12
 GROSS 1179 Owners Nederl Indis Tanks Maats Owners' Address
 UNDER DE. 760 Managers Anglo-Batavia Steamship Co. (If not already recorded in Appendix to Register Book).
 NET 704 Port belonging to Batavia

Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Kippel Harbour Destined Voyage
 WB=CellDBorDBa feet; uE&B feet; f feet
 total capacity tons. FPT tons; APT 31 tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
 If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 4812 Port Sing

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
 CHARACTER. Date of last Survey and of Periodical Surveys.
 Machinery and Boiler Surveys (including date of N.B., if any).
+100 A1 +LMC 5.27
S.S. H.K.G. 12 3-5, 23 +LMC (M) 3.29
S.S. H.K.G. 12 1-26 TS 12.30
Sing 12.30
Carly petrol in bulk

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined ☒ 11/2

Was a damage report made by anyone else? If so, by whom? ☒

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking.

ow done— Vessel placed in dry dock; Bottom and Rudder cleaned, examined and recoiled.

panis— Three doubling plates fitted to shell plating in way of engine room where plating locally wasted. A few minor deck repairs carried out.

oli. This vessel has now been laid up at Singapore.

SUMMARY OF DAMAGE REPAIRS	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dr. Plates.	Other Items:—
Removed								
Removed and Fitted or Repaired								
Fitted or Repaired in place								

ASBEST CONDITION OF THE	State if Tanks have been examined inside	Dging. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
Use of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Well)
Stings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	When put on, Month Year
Use of Fastenings	Ceiling	Scuppers	Boats
Side Plating	Cement or Asphalt (State which.)	Charge Hatchways	Masts, Yards, &c.
Stanchions	Rudder	Hatches	Condition, how ascertained
Stems	Steering gear and its connections	Planking of Wood Vessels	(State if wedges removed)
Stems	Windlass	Caulking	Sails
Stems	Have Pumps now been examined and found efficient?	Treesails	Equipment letter
Stems	Have Slides Valves now been examined and found efficient?	Breasthooks & Stemson	Anchors, No. of
Stems	Have Watertight Doors now been examined and found efficient?	Transoms, Painters, & Crutches	Cables (State if now ranged)
Stems	Have Ventilators and their Connections been examined and found efficient?	Timbers of Frames at openings	„ length
Stems		Ditto ditto at other places	„ Rule length
Stems		Stringers, Clamps & Shells	Hawser & Warps
Stems		Saltg	Standing and Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.24," or "to remain as classed and to have record of survey, 1.24, and the notations of ss No. 1-24 and ptdp24, &c."

This vessel is eligible in my opinion to remain as now classed in the Register Book without fresh record of survey

Survey Fee (per Section 29)	\$40/-	Fees applied for	23/7/31
Special Damage or Repair Fee (if any)		Received by me.	
Travelling Expenses (if chargeable)	\$5/-		
Second Surveyor's Fee (if any)			

Committee's Minute: THE 25 AUG 1931

Character Assigned: Deferred for

John L. Malay

Surveyor to Lloyd's Register of Shipping.



© 2020

Lloyd's Register Foundation

W680-0191