

11 - MAR 1933

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel Sc. "MICHALAKIS"

Rpt. Msl No. 8122

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Signature of Survey

Action has been deferred for examination in dry dock and repairs to bilge keel, port side, after grounding.

The 3rd S.S. No.1, became due 12,32, and a proposal to carry out same within the year of grace has been agreed to.

Repairs were required to the rudder.

The Marseilles Surveyors now report the vessel placed in dry dock and the requirements of the Special Survey partly complied with.

The bottom has been cleaned and coated and repairs and renewals effected to floors, tank top and girders, decks, bunker casing, rudder etc.

On account of damage through grounding, repairs have been effected to the bilge keels.

The Surveyors recommend 15 fathoms of chain cable be supplied to replace worn cable.

It is submitted action be deferred.

S.R.L. Delete "dry docking & rudder".
INSERT "CHAIN CABLE."

W681-0092



© 2020
Lloyd's Register
Foundation

Survey Re
Special Dr
Travelling