

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

22nd August, 1933.

Dear Sirs,

8. With reference to the classification in the Society's Register Book of the steamer "TRECTI", I beg to acquaint you that the Committee have had before them to-day a report received from the Society's Surveyor at Split, from which it appears that the vessel has been examined afloat and by a diver after grounding.

Soundings were taken and so far as could be ascertained no damage or leakage has been sustained, but it is recommended that the vessel be placed in dry dock for further examination at the first convenient opportunity.

I may add that the vessel's class is also subject to a bower anchor being supplied and to the after mast being permanently repaired at the first convenient opportunity, as previously recommended.

I have further to add that to complete the Boiler Survey of this vessel, which became due at the end of last month and was partly held at Rotterdam in March the port boiler requires to be examined and all the safety valves adjusted under steam.

8. Prvo Dalmatinsko Trgovacko Drustvo,
DUBROVNIK 2,
Yugoslavia

I am, Dear Sirs,
Yours faithfully,

Clerk to the

Lloyd's Register
Foundation