

W682-0202

19 AUG 1933

by Chief Ship Surveyor

Received from Chief Ship Surveyor

S NAME Steel Sc. "TRECI" Rpt. Spt. No. 217

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Survey

The class is subject to a bower anchor being supplied and the after mast being permanently repaired at the first convenient opportunity.

The Split Surveyor reports this vessel examined afloat and by a diver after grounding, soundings taken and so far as could be ascertained no damage or leakage appears to have been sustained.

The Surveyor, however, recommends the vessel be placed in dry dock for further examination at the first convenient opportunity.

It is submitted action be deferred and the Owners informed of the Surveyor's recommendation.



© 2020

Lloyd's Register  
Foundation

18.8.33