

COPY.

Lloyd's Register of Shipping.



Port of SPLIT.

8th. August. 1933.

This is to Certify that I have

Surveyed the Steel Screw "TREBİ", 3819 Gross Tons of Dubrovnik, whilst afloat at Sibenik, on account of possible damage alleged sustained through vessel grounding whilst loading at Sibenik on the 6th. August, 1933.

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, ~~stating that all repairs recommended by me have been completed to my satisfaction, and~~ that I have Recommended that she be continued as classed

in the Register Book, subject to the vessel being placed in dry dock for further examination at the first convenient opportunity: to having a bower anchor supplied and the after mast permanently repaired at first convenient opportunity, and without fresh record of survey

being fit to carry dry and perishable cargoes.

To complete the Boiler Survey for record BS 3.33, the port boiler has to be surveyed and all safety valves adjusted under steam.

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

