

Did the Surveyor personally go inside each Main Boiler separately and make a thorough examination at this time?

W682-0271

Inspected by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

2E  
17 JUL 1933

SEL'S NAME

Agios Ioannis

Rpt.

Ret

No. 22236

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. - Extract from Sub-Committee's Report, 24/5/92.)

Result of Survey

COMPLETION OF SPECIAL SURVEY OF ~~ENGINES AND BOILERS~~ FOR S.S. No.

This Survey, due

9.32

now  
partly

held

10.32

now

~~completed, and the following repairs carried out (due to~~

):-


It is submitted the vessel is eligible to remain as classed, with

notation of

B.S. 10.32.

as recommended.

Subject to the  
ONKEY BOILER  
not being used again.



© 2020

Lloyd's Register  
Foundation