

Ship Surveyor

Received from Chief Ship Surveyor

21 NOV 1924

S.S. No. 1 "DALE SIDE"

Rpt.

Sld

No. 28955

s of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points pointed in the endorsement."—Extract from Sub-Committee's Report, 34/5/92.)

S.S. No. 1 AND DAMAGE

e through Grounding & striking keel

repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
red	1						
ed and faired repaired.....	13						
d or repaired place.....	5	7					

items:-

vessel placed in drydock, bottom cleaned & coated
Bilge Keels repaired and minor repairs effected.

e 1st S.S. No. 1 has also been held and following repairs done
o wear and tear:- minor repairs effected.

is submitted the vessel is worthy to remain classed with record
rvey 11.24 Sld and notation of S.S. Sld M1-24
commended.

100 A.I.

11.24 Sld

S.S. Sld M1-24



© 2020
20.11.24
Lloyd's Register
Foundation