

W687-0206

F.E.

Received by Chief Ship Surveyor 30.1.07

Received from Chief Ship Surveyor _____

VESSEL'S NAME Sa. S. S. "Westhampton" Rpt. Ses No. 23136

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<u>2/20"</u>	<u>Proportion</u>
Spar Sheerstrake . .	<u>1</u>	<u>1</u>
Description of Framing:— <u>Deep (Bulb angle) framing.</u> (viz., ordinary, deep, zed, channel or bulb-angle).		

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100 A 1 ("Steel") as recommended.


 \pm 100 A 1 ("Steel")1 DR (Stt) \pm deep framing.N. B—Cell DBa \times u E 110' f 110' 4586 APT 305

FK 484 Cen. Lloyd's A & CP P25' B64' F28'

C. H. J.
30/1/07

© 2020

The Surveyor should be requested to forward the letter from Lloyd's Register to the mission of ceiling as this does not appear to have been forwarded with the first entry report. C. H. J.



Lloyd's Register Foundation