

2m, 12, 12.

In dam

31 MAR 1924

2

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stu L Se* "COVADONGA"

Rpt. *Bbo*

No. *6429*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

S.S. No. *1*

The S.S. No. *1* has now been held, and the following repairs done due to wear and tear:-

vessel placed in drydock. bottom examined + recoated. + minor repairs effected.

The Surveyor reports 150 fathoms of 1" dia Chain Cable on board, and it is the owners intention to test the anchors and supply new cables to obtain the fig I.

It is submitted the vessel is worthy to remain as classed, with record of Survey *3-24 Bbo* and notation of *S.S. Bbo No 1-24* as recommended.

100 A-

3-24 Bbo

S.S. Bbo No 1-24

31/3/24



© 2021

Lloyd's Register
Foundation

W688 F0027