

Angles to outside plating.....	3 $\frac{1}{2}$	3 $\frac{1}{2}$	.41	3 $\frac{1}{2}$	3 $\frac{1}{2}$	.41
to floors .....	3	3	.41	3	3	.41

Angles on ditto, No.  
 Tie Plates outside Hatchways  
 W69-0033

S.S. "OLDEKERK".

It is submitted that an inclusive fee of £100 be charged for the survey of the hull, and an inclusive fee of £50 be charged for the survey of the machinery, and no additional fee should be charged for freeboard assignment.



© 2020

2.11.21.

Lloyd's Register  
 Foundation

\* If Iron or Steel Deck, state if whole or