

W69-0120

4 E

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

"PINDOS".

EL'S NAME

Cff.

53402.

Rpt.

No.

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

e of Survey


~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

S.S.No.2, due 8,39 partly held.(completion within the year of grace-approved.)

Minor repairs to electric circuits effected.

It is submitted the vessel is eligible to remain as classed without fresh record.

S.R.L.:- Note examination of electrical equipment, windlass and steering engine as part S.S.



© 2020

Lloyd's Register
Foundation

6.5.40.