


TELEGRAM received from the Surveyor at COPENHAGEN.

of receipt: 10.11.31.

TRANSLATION.

PETSAMO - Vessel's Name

ERFOW - Referring to your cable of
TIVIT - yesterday
OKVUW - regarding
ALUHD - main boilers
SAGXU - steel
NEJLE - plugs
ETYRX - caulked
KEBEZ - from
MUECI -
ESYSE - ~~could~~ be removed *cannot*
SRAIX - unless
GHEXA - disturb
 threads
KYBUZ - in
KUFGA - holes
MAGYP - necessitate
SAXAN -
LIHDA - larger
NEJLE - plugs
SAZPO - stop
EPKET - Buttstrap(s)
PHUAT - specially
JESDU - examined
LATHI - internally and externally
ADIMT - and
JYKAX - found in good condition
SAZPO - stop
WNYES - Owners
LYKYP - most
SUCMI - urgently
ORWOX - request
MARJE - not
SMOIJ - to
OLTHU - remove
NEJLE - plugs
 Burmeister
FASJY - consider
JUMAV - fitting of
OVMUG - rivets
LYKYP - most
SRYON - unsatisfactory
MYWID - Plans forwarded
SNEPI - today.



© 2020

Lloyd's Register
Foundation

Wb9-0176

Submitted action referred
until receipt of plans.
H. S. H.

10m.7.30.
ited not to writ

Special Damage or Repair Fee (if any)
(per sec. 20)
Travelling Expenses (if chargeable)

ASJYJ

SUCM

PHU

KYB

ETVR

= PE

= CO

KÖBEN

16.11

COUNTRIES S

100 WALL 8160.

(30 lines)

TELEPHONE

1,000,000, Ltd.



© 2020

Lloyd's Register
Foundation