

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

S NAME

Pitamo

Rpt.

Cm

No. 8665

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

Survey COMPLETION OF SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 3.

This Survey, due 9.31 ~~partly held at~~

now

completed, and the following repairs carried out (due to clam. & wear/tear):-
 Damage due to grounding. Stern shaft changed. A number of Condenser
 s renewed. Pumps overhauled & placed in order.
 Air wear & tear repairs effected.
 All defective rivets in both straps of the main boilers: renewed
 & plating and straps examined in way of the rivets, ^{holes} prior
 renewal and found in good condition.
 Minor repairs effected to boilers.

It is submitted the vessel is eligible to remain as classed, with
 extension of 1 Year 11.31 as recommended. Subject

S.N. 11.31

the rivets in the lower longitudinal Beams of all boilers
 being specially examined before end of 5.32

YKm

14.12.31



© 2020

Lloyd's Register
 Foundation

W69-0191