

W692-0114

5m.9.37.

1

Sent to Chief Surveyors .....

Received from Chief Surveyors .....

VESSEL'S NAME Lonsdale Report LW No. 111412


**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey Grounding When due -

The vessel requires to be dry docked for further examination after grounding, at first convenient opportunity.

PLATING to be DRILLED when vessel is 36 years old, or at next Special Survey thereafter.



Lloyd's Register Foundation

S.R.L. insert drydocking (grounding)