

GRAMS: REGISTER LIVERPOOL.

TELEPHONE: CENTRAL 5281 & 5282.



Lloyd's Register of Shipping.

201, Tower Building,

Liverpool, 16th November 1921.

Reference

Dear Sir,

With reference to the Secretary's letter of the 15th inst respecting the Steamer " CONISTON " Liverpool First Entry Report No.82966 I have to state that the size of the upper and raised quarter deck stringer angles is as approved, and in the sister vessel, and not as reported. The thickness of the boss plate is .34 and the scantlings of the bridge deck stringer, stringer angle and plating as as required.

Regretting these errors were made on the report.

I am, Dear Sir,

Yours faithfully.

The Secretary.

LIVERPOOL.



© 2021

Lloyd's Register
W693-0145
Foundation

S. Poop Deck, Angle, Bulb Angle, Plate,)	5/2	3	30	5	3	30	Bridge Deck Stringer Plate, br'dth & thickness
Tee Bulb, or Channel)							" Angle on ditto.....
Angles on upper edge							