

An Air Steam pipe renewed.
4 feed pipes repaired.
The vessel is en route to Japan for
recognition.

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

NP Line 3-31

Submitted action be
deferred.

2A
14/1/34

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020

Lloyd's Register
Foundation