

Received from Mr.
COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

3rd September, 1921.

Dear Sir,

With reference to your First Entry Report No.14680 on the S.S."T.H.SKOGLAND", I shall be glad if you will be good enough to state whether the deep tank has been examined; the riveting of the butts of the side and bottom shell plating has been specially examined: you have satisfied yourself regarding the pillaring arrangements and construction of the cargo doors: the thickness of the centre girder and of the shelter deck plating in way of the openings are as approved: the anchors and chain cables have been tested by Surveyors to the Germanischer Lloyd, and whether you are correct in stating that the chain cables have not been ranged in view of the particulars of tests &c., entered on your report.

I am, Dear Sir,

Yours faithfully,

Secretary.

Geo.Dykes, Esq.,

HAMBURG.



© 2021

Lloyd's Register
Foundation

W694 - 0124

Round up of
Dk. Beam,

hes.
e in
ip. Inches
Spacing
Ship.

up in
the Span
need 8

up in
Ship, in S

0125

80a.

ittec.

lon

been

of the

on of

r deck

d chain

they

rst