

Port of COLOMBO,

11th March 1921.

SURVEY REPORT - S.S. "JAVARY".

THIS IS TO CERTIFY THAT I, the undersigned, have made a careful examination of the repairs on the port main boiler of the above vessel, recommended by me in my report of the 6th instant, and found the work carried out to my satisfaction. The saddle and wrapper plate landings of this boiler have been treated at some previous time by the Electric welding process, and as the vessel is sailing for Home Ports, I strongly recommend that the welding be removed, rivets cut out and seams drawn up and reriveted at the earliest opportunity convenient to Owners.

AB Campbell

Actg. Lloyd's Surveyor.



© 2021

Lloyd's Register
Foundation

20 MAY 1921

ferred to Mr. May no.

УВАЖАЈТЕ СЕ ПОСРЕДСТВОМ НАЈБОЉЕГ

topg, a gillnet.

© 2021

Lloyd's Register
Foundation