

equipment generally examined and found of now placed in good condition and all holds cle
coated.

cially examined and found in good condition.

5m.9.24.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

F 4 FEB 1929

VESSEL'S NAME Stl. s.s. "TENSHO MARU". Rpt. Kob. No 5090

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Kobe Surveyors report this vessel placed in dry dock, bottom cleaned and coated, one bridge deck plate partly renewed and minor repairs effected.

It is submitted the vessel appears worthy to remain as classed with record of survey 12-25 as recommended.

100 A1

12.25 Kob.

4.2.26. © 2020

Lloyd's Register
Foundation

W695-0027

Special Damage or repairs (per Sec. 29)
Travelling Expenses (if chargeable)
incl'dg. MC & TS.
Second Surveyor's Fee (if any)

Received by me,

19

Surveyor to Lloyd's Register of SH