

L698-0042

*Handwritten scribbles*

**PRINCESS.** — Calcutta, June 5. — Steamer Princess sailed June 3 for London, with passengers and cargo, reports by wireless returning Sandheads boilers leaking; steering gear defective.

*Submitted that Surveyor should be requested to report.*

*Noted  
ARR  
13.6.19*

*JMM 25/7/19*

*Await further report  
tele next mail*

*JMM*

*no report received by  
to-day's mail.*

*JMM  
21/7/19*



© 2020 Lloyd's Register Foundation

cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for the  
ed? Was a damage report made by anyone else? If so, by whom?