

"ROYAL GEORGE" from which I note that the classification of the vessel at the end of the bridge requires to be

508/12.

11 JAN 1921

to Chief Surveyors 11.1.21.

Received from Chief Surveyors

SEL'S NAME Atk 20. Royal George Report Lon. No. 10599

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/6/92.

re of Survey

When due

Notes
M
11.1.21

To Mr. P. A. Hill
to note. 12.1.21



© 2020

Lloyd's Register
Foundation

W648-0185

Vessels

ed.
mored

anged

rging

k conse
to hav

re 2

RLS

of Ship