

W698-0186

16 JUN 1920

by Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *M. T. S. S. Royal George* Rpt. *Don* No. *10599*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

Docking

The class is subject to permanent repairs being effected to sheerstrake plating on each side, at fore end of bridge

The Southampton Surveyors report the vessel examined in dry dock, the bottoms cleaned & coated and minor riveting repairs etc. effected

It is submitted the vessel appears worthy to remain as classed, with record of survey, as recommended, subject as above. *© 2020*
100 H1 Shelter Dk. w/od. } Subj. etc. M. J. 1920
to Don.

The Surveyors attention should be directed to Circular No. 1339 regarding special examination of ventilators and their foundations.

Expenses (if chargeable) £

19

Surveyor's Fee (if any) £

A. Elliott

Surveyor to Lloyd's Register of Sh