


L. S. Kanto Pasubio

Gen PS-F4.

Submitted that before dealing with this case
the Genoa Surveyors should be requested to state
whether the new donkey boilers have now
properly secured on board, their mountings
& safety valves fitted, they should also forward
particulars of the safety valves & state whether
they are fitted with easing gear.

H.
4/3/24

Oliver L. Gen. 7/3/24



© 2020

Lloyd's Register
Foundation

W699 9098

subject to annual survey of W.T.B.

Note. Tail Shaft (C-L) N