

PHONE: NAT. No. 648.



Lloyd's Register of British & Foreign Shipping,

Royal Exchange,

Middlesbrough, 26th August, 1907.

The Secretary,
LONDON.

Sir,

I have to report that on examining the 3 stockless bow
Anchors supplied for the new steamer "BALTIQ SEA", Messrs. Craig
Taylor & Co's No.125, a deficiency of 23 lbs was observed in the
collective weight.

follows.:-

Anchors Supplied

39 - 0 - 5

38 - 1 - 7

32 - 1 - 21

109 - 3 - 5 Equipment letter (S)

Table 22

38 - 3 - 0

38 - 3 - 0

32 - 2 - 0

110 - 0 - 0

As the vessel is approaching completion it is requested
that the Committee's decision may be wired to this office.

I am, Sir,

Your obedient servant,

W. H. Cooper



© 2020

Lloyd's Register
Foundation

W699-0061

Hold	3 3/4	48	3 3/4	48
Quarter, 'tween Dks.,				

Deck, material and thickness
Forecastle Deck Stringer Plate, brdth & thickness
Angle on ditto

Referred to the Chief Ship Surveyor.

F. A. No.

AUG 27 1907

Wire requested

? for class.
Comm.
to day



© 2020

Lloyd's Register
Foundation