

F.E.

...ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME *Stl S M/V* " *BORGNY* Rpt. *Cfn* No. *7931*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(\*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/02.)

*1st Long*  
 Transverse No. *5642* Depth "d" *✓*  
 Framing: Table No. *✓* Description *Longitudinal framing*  
 Longitudinal No. *20892*  
 Proportions Length *16.05*  
 Depth =  
~~Deck~~ Sheerstrake *as approved*

*Revised Rule*

5800-FM

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100A.1. (Steel). Carrying Petroleum in bulk.  
 10" (Stl) web frame, Longitudinal framing Bracketless System  
 Cell D.B. v E 47' 50t, D.T. 29' 210t, F.P.T. 154t, A.P.T. 225.  
 F.K. 12 B.H. pt Cem. Drydo ARCP.  
 P 67' B 38' F 31' Machinery aft  
 TRUNK IN WELLS.

*[Signature]*

*[Signature]*  
19.4.29

*19/4/29*

The Surveyor should be requested to forward a copy of the midship section of the vessel as built.



© 2021

Lloyd's Register Foundation