

23. 3. 22

Received from Chief Surveyors

Sl. No. 1000  
E. M. L. Issoira

Report in 22 MAR 1922  
No. 5326

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

which have to be submitted to the Clasing Committee "the endorsement to contain a succinct summary of any repairs that have been made and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case of the Clasing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22.

Repairs

When due

B.S. due 8/21

Joint on screw shaft (to be specially examined at joints of liners) expired 2. 22


H.P. Cylinder covers to renew

Notes

a. Hill

M. L. 21. 3. 22

22. 3. 22.



© 2021

Lloyd's Register  
Foundation

0039