

10 MAR 1922

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "HOPELYN"

Rpt. Nwc.

No. 75261

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The class is subject to permanent repairs being effected in way of some slight leakage in No.1 hold well.

The Newcastle Surveyors now report the vessel has sustained damage to shell plating etc. through ice.

Temporary repairs have been effected and it is recommended permanent repairs be carried out at the first suitable opportunity.

The Special Survey No.1 became due 2,22 and it is stated this will be held within the year of grace.

It is submitted the vessel appears worthy to remain as classed without record of survey subject as above and subject to damage through ice being permanently repaired.

As in. subject


Large bottom not fitted

M

2.3.22.

W702

0218



© 2021

wrecked 10/22
Lloyd's Register
Foundation