



LONDON.

13th. August 1923.

5m,1.23.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

17 AUG 1923

VESSEL'S NAME Stl. s.s. "BISHOPSTON"

Rpt. Sld. No 28631

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

The Sunderland Surveyors report this vessel to have sustained damage to shell plating, etc. on port side through collision and recommend that the necessary repairs be carried out at the first convenient opportunity.

It is submitted the vessel appears worthy to remain as classed without record of survey, subject to the damaged shell plating, etc. on port side being dealt with at the first convenient opportunity, as recommended.

As now. Subject -.

AD.

16.8.23.

The Certificate of Classification, to be endorsed
"Cargo battens not fitted," and the same
notation to be printed in the Register Book,



Lloyd's Register
Foundation
W703-0080