

25 MAR 1927

Received from Chief Ship Surveyor

Ship Surveyor

NAME S.S. "GALAVA"

Rpt. Syd.

No. 9645

Reports of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.

2nd S.S. No. 2 AND DAMAGE.

through Collision

failed as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
.....	1 (H)	1					1
and failed							
failed.....							
or repaired	2				1		
ce.....							

Remarks:- Stem bar failed in place & minor repairs effected

S.S. No. 2 has also been held and following repairs done

ear and tear:- vessel placed on slipway, bottom cleaned & coated. renewals effected to framing, shell, decks, hatches, casing. Considered necessary.

1 ton of chain cable of proper size, weight & test placed on board to replace amount worn to below the Rule minimum size. submitted the vessel is worthy to remain as classed with record


227 and notation of S.S. Syd No 2-27.

ended.

O.A.I.

27 Syd

Syd No 2-27



Surveyor to Lloyd's Register

MAR 29 1927