





2-23. part held.  
Action not stated.

It is submitted that this  
will be eligible  
for record. As 9.23 when the  
forward boiler + its mountings  
have been examined +  
all safety valves adjusted

B.A.

8/9/23

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.



© 2020

Lloyd's Register  
Foundation