

W704-0223

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

SHIP'S NAME Steel SS "RUDELSBURG" Rpt. N.Yk. No. 19669

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey _____

This vessel was built in 1916 and classed with Germanischer Lloyd.
The notation LOR 10,20 has been assigned.

The New York surveyors now report a new lower anchor supplied & that
30 fathoms of chain cable is missing



© 2020

Lloyd's Register
Foundation

aes
21-1-21